

Ultrasonic Distance Measure UDM-1



Configuration Overview | 4.8.0 / 2024.01

UDM-1 Distance Measure

Ultrasonic Distance Measure UDM-1 Set
[K0.60055.0](#)
Set includes:
UDM Sensor Unit, K2.65130.0
UDM Display Unit, K2.65131.0
Cable UDM-Sensor, K2.0006459



Cable UDM-PSC (1,5m/5ft)
[K2.65262.0](#) (yellow cable)
Additional PSC power cable needed

PSC Power Cable

PSC Cable System:
Both needed:
PSC cable to device
PSC power cable to power source

ARRI PSC power supply cables
K2.65206.0 PSC-XLR3 1,5m/5ft 1,5m/5ft 24 Volts battery
K2.65207.0 PSC-XLR4 1,5m/5ft 1,5m/5ft 12 Volts battery
K2.65211.0 PSC-RS 0,6m/2ft 0,6m/2ft ARRI RS socket
K2.65212.0 PSC-FI2 0,6m/2ft 1,5m/5ft ARRI OBB-2 battery

Cable UDM-UMC (1,5m/5ft)
[K2.65144.0](#) (yellow cable)

Connects to CUB-1

Cable UDM - EXT (16p)
(0.5m/1.6ft) [K2.65261.0](#) (yellow cable)
Connects to EXT socket of ALEXA cameras with SUP 8.0 or later

Cable UDM - SERIAL (7p) (1.5m/5ft),
[K2.65144.0](#) (yellow cable)

Connects to UMC-4

Cable UDM - SERIAL (4p) (0.8m/2.6ft)
[K2.0041172](#)

Connects to RIA-1

Cable UDM-RS (1,5m/5ft)
[K2.65240.0](#) (yellow cable)
Connects to camera RS socket

Cable UDM-D.Tap (0,8m/2,6ft)
[K2.0023553](#)

Cable UDM-UMC (1,5m/5ft)
[K2.65144.0](#) (yellow cable)

Connects to CUB-1



LCUBE CUB-1 Basic Set
[KK.0009001](#)



ALEXA



AMIRA



LCUBE CUB-1 Basic Set
[KK.0009001](#)



LBUS 0.2m/8", [K2.0006749](#)
LBUS 0.3m/1ft, [K2.0006750](#)
LBUS 0.5m/1.5ft, [K2.0006751](#)
LBUS 0.8m/2.5ft, [K2.0006752](#)
LBUS 1.5m/5ft, [K2.0006753](#)
LBUS 3m/10ft, [K2.0006754](#)
LBUS 6m/20ft, [K2.0006755](#)
LBUS 15m/49ft, [K2.0006756](#)



cforce motors



ALEXA Mini /
ALEXA Mini LF

Focus Tracking

UDM values / Lens Data

WCU-4



Wireless Compact Unit
WCU-4, [K2.72103.0](#)

Hi-5



Hi-5 Hand Unit Body
Set, [KK.0039973](#)
Radio Module needed

UDM values / Lens Data

Focus Tracking

UDM values / Lens Data

Focus Tracking

UDM values /
no Lens Data

Cable CAM (10p) - RS (3p) (0.5m/1.6ft), [K2.0001606](#)



AMC-1



LBUS LBUS